







A		10x40	16
C		M6x120	20
G		M6x16	20
L		3,5x35	30
N		Ø16	4
P		Ø8	8
Q		Ø10	8
S		4mm hex	1





3







4






A		10x40	4
C		M6x120	2
G		M6x16	2
S		4mm hex	1






A		Ø10x40mm	16	K		Ø16	4
C		M6x120mm	20	L		Ø10	8
F		M6x10x14mm	20	M		Ø8	8
H		6,3x70mm	2	N		4mm hex	1
J		3,5x35mm	30	Q			2
O		3,5x15mm	20	R			2



1




2 x




2







3




4






			N	P	R	S	T	U
			M6x40	M6x8x15	D8	D10	N4	N6
								
			x2	x1	x8	x12	x1	x1
A	B	C	D	E	G	H	K	M
Ø10x50	Ø16x75	M6x10x13	4x60	6,3x70	M6x11x20	M6x120	M6x100	M6x60
								
x10	x6	x10	x16	x20	x2	x9	x1	x1


1




2




3




Dx14






4



5



6



7

